DART SERVICE INSTRUCTION

TO AMEND INSTALLATION INSTRUCTIONS IIN-D427-659 Rev. A AND INSTRUCTIONS FOR CONTINUED AIRWORTHINESS ICA-D427-659 REV. 0

REF CANADIAN STC: SH02-19 REF FAA STC: SR01532NY REF JCAB STC: STC-151-TYO

It has come to Dart's attention that interference between the Ground Handling Wheels and the D3004-1 Center Section Ski may exist when using OEM Ground Handling Wheels. It is acceptable to trim the D3004-1 Center Section Ski to remove the interference as shown in Figure 1 of this DART Service Instruction.




Figure 1 - Center ski trimming details

CANADA DEPARTMENT OF TRANSPORT AIRCRAFT CERTIFICATION BRANCH DAO # 01-O-01						
BY: D. SHEPHERD (DE # 02)						
DATE: 12.01.10 CERT. NO.: SH02-19 ISSUE NO.: 1						

A	NEW ISSUE				12.01.10	
REV.	DESCRIPTION			BY	DATE	
DESIGN		AP	DART AEROSPAC		FITD	
DRAWN		AP	HAWKESBURY, ONTARIO, CANADA			
CHECKED		1	DRAWING NO.	· · · · ·	REV. A	
MFG. APPR.		N/A A	DSI 9589	;	SHEET 1 OF 1	
APPROVED		M	TITLE		SCALE	
DE APPR.		#	CENTER SKI MODIFICATION		NTS	
12.01.10			COPYRIGHT © 2012 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON MITHOUT WRITTEN PERMISSION FROM DATE AEROSPACE LTD.			